										7 !	EER 10	
1. CASE NUMBER 2. INVI 951214CCC1255 H 95R00 & C				3 3 5 9 3. OFFICE CODE 8 0 0				EPIDEMIOLOGIC				
				IDI INITIATED 9	INVESTIGATION REPORT							
6. SYNOPSIS OF INCIDE	ENT OR C	OMPL	AINT				<i>i</i> .					
A toaster oven started flames self-extinguish returned the toaster or	ed and th	here w	vere no inj	o flames while t juries, deaths, o	the c onsum or fire/sma	der was e oke dama	oolting to ge to the	wo slices residenc	of breader. Th	ad. The	ner	
											-	
7. LOCATION Home	1	1 0	8. CITY	Morr Dei	4 - !		9. STA					
10A. FIRST PRODUCT			<u></u>	New Brit		E MODEL		T	TACTUR	CD 8 400	2500	
Toaster Oven	(0	2 1 6	Black & Deck 6 Armstrong I Shelton, CT 0	er – Unkr Rd	nown Mo	del Num	ber	·ACION	EK & AUU	KESS	
10B. SECOND PRODUC	7		- J .	11B. TRADE/BR	RAND NAM	E, MODEL	NUMBER	, MANUF	ACTUR	ER & ADD	RES\$	
None Electric	s/Recp	₹. 5	061				NONE					
12. AGE OF VICTIM 9 9 9	13. SEX no injury			9	14. DISPOSITION 9 no injury			15. INJU no injur		GNOSIS	70	
<i>16. BODY PART</i> No injury	0 0	17. F	RESPONDE/ plainant	NT(S)	1			ON TYPE 19. TIME SPENT 2 4. 0				
20. ATTACHMENTS No Attachments		0	21. CASE Hotline	SOURCE			SEWED BY		9 <u>6</u>		PAY 23	
23. PERMISSION TO DI CPSC MA				NAME	•	IAY N	OT DIS	CLOSI	E MY	NAME	<u>X</u>	
24. NARRATIVE (See In	structions	on Pa	age 2)	1.1	197	25. REGI	ONAL DIF	RECTOR R	REVIEW	30/4	ATE	
	W	EKI ^{FF}	10 1 00 m	Common and Common has not further not	is du participal de la constant de l		<i>•</i>					
											-	

(USE ADDITIONAL SHEETS IF NECESSARY)

951214CCC1255 Page 1

PRE-INCIDENT:

The complainant is a 48 year-old female. She stated that during the period October, 1994 (the exact date of purchase could not be confirmed by the complainant) through November, 5 1995 there were no problems with the toaster oven. At the time of the incident the complainant was toasting two pieces of unbuttered bread in the toaster oven. There were no injuries or deaths associated with this incident.

The complainant stated that the toaster oven was purchased in November, 1994 from a local retail store. The toaster oven was used daily after its purchase without incident until November 6, 1995; the date of the incident. Just prior to the incident, the complainant placed two pieces of unbuttered toast into the toaster oven and pushed down the "toast lever".

INCIDENT:

After approximately 2 minutes the complainant noticed smoke and flames escaping from between the front glass section and the top of the toaster oven. The flames were approximately "several inches" above the top of the toaster oven. The complainant stated that the toaster usually automatically cuts off or "pops" after 1 minute. In this incident the toast lever did NOT move to the off position.

POST INCIDENT:

The complainant moved immediately after noticing the flames and unplugged the toaster oven. Several minutes after unplugging the unit the flames self-extinguished. The complainant plugged the unit back in several hours after the incident but the unit did not respond; it was damaged in the fire. There were no articles on the top surface of the toaster oven prior to the incident.

The complainant stated that the toaster oven was used on a daily basis and on occasion it was used several times daily. She added that the unit was cleaned regularly and that the unit was "clean" prior to the incident. The complainant returned the product to the retail store where it was purchased several days after the incident. The clerk at the store was unsympathetic about the incident and did not offer the complainant a refund or an exchange. The complainant purchased a similar model (same brand name) toaster oven at a different retailer in December, 1995 and has had no problems with the new toaster oven. The complainant checked the current toaster oven for a model number but could not locate a specific model number on the new unit.

PRODUCT IDENTIFICATION:

NOTE: The product was not available for collection; it was returned to the place of purchase.

From the information received from the complainant the product was a toaster oven, imported by:

Black & Decker 6 Armstrong Rd. Shelton, CT 06484

The toaster oven had a broil and a defrost feature. The complainant purchased the product for \$39.99 at:

Caldor Farmington Ave. New Britain, CT

Bill Kennely
ACCIDENT INVESTIGATION REQUEST FORM OF THE OFFICE OF THE O
Document Number 495 B008640 57
Date of Incident 1 495 Category I.D SELT 3/996
Pollow-Up Requested Hazard Analysis Section 15
Type Follow-Up Requested Telephone Call On-Site
Headquarters Contact Jeanne Siebert
Assignment Message Plase determine detaily
and collect sample. Please ask:
Duhue were the flames escaping from
exactivey?
2) what was me under of me cumb
thay (diety of lean? How diety)
3) tow often was The toasty over used.
4) How often is the toaster over weared?
5) How much bread was being toasted?
Was it buttered?
Dwas true any thing on top of Me toasta over?
Person(s) to Contact (CNSUM)
Guideline
•
Requested By Jaanne Siebert
Task Number 96/2/4000 1253
Assigned to NYCO Date 12/14/95

11- 2

CONSUMER PRODUCT INCIDENT REPORT

CUUT ET VUN

Region: EASTERN

(WORK) 2. PHONE NO. (HOME) NAME OF RESPONDENT none TO THE PARTY STATE ZIP CODE 4. CITY ADDRESS New Britain CT 06051 DESCRIBE INCIDENT OR HAZARD, INCLUDING DATA ON INJURIES mead was toasting in toaster oven for 2 minutes on light setting (toast itton didn't automatically pop up to shut off toaster) when mother saw noke and flames (height unknown) coming from the front of oven. Consumer uplugged oven, removed burnt toast and flames self-extinguished within a ouple of minutes. No one was injured. Toaster oven is UL listed. -cont-7. IF INJURY OR NEAR MISS OBTAIN AGE/SEX 8. IF VICTIM DIFFERENT FROM DATE RESPONDENT, PROVIDE NAME O Y/N OE, AND DESCRIBE INJURY: NCIDENTS RELATIONSHIP 1/6/95 none none 10. BRAND NAME DESCRIPTION OF PRODUCT Black & Decker lectric toaster oven 12. MODEL, SERIAL NUMBERS 1. MFR/DISTRIBUTOR NAME, ADDR. & PHONE unknown lack & Decker nknown 13. DEALER'S NAME, ADDRESS & PHONE nknown Caldor 00-231-9786 Farmington Ave. nknown New Britain, CT 00000 nknown unknown nknown 4. WAS THE PRODUCT DAMAGED, REPAIRED OR 15. PRODUCT PURCHASED NEW x USED MODIFIED? YES x NO IF YES, BEFORE DATE PURCHASED '94 AGE 1 year DESCRIBE: OR AFTER THE INCIDENT? after 16. DOES PRODUCT HAVE WARNING LABELS? lamaged: inner & outer (top) of oven are IF SO, NOTE: unknown purned 19. MAY WE 18. IS THE PRODUCT STILL 7. HAVE YOU CONTACTED THE YES x USE YOUR NAME NO xAVAILABLE? IANUFACTURER? YES -WITH THIS IF NOT, DO YOU PLAN TO CONTACT IF NOT, ITS DISPOSITION 11/95 may return to mfr. for REPORT? THEM? YES x NO OTHER? NO YES x refund FOR ADMINISTRATION USE RECEIVED BY (NAME & OFFICE) 22. DOCUMENT NO. 20. DATE RECEIVED 21. H95B0086A 11/09/95 1dm/HL 24. PRODUCT CODE(S) FOLLOW-UP ACTION 95/214 CCC/253 0216 ENDORSER'S NAME & TITLE DISTRIBUTION CTW 11/9/1995

CPSC FORM 175 (9/89)

951214 CCC/258

CONSUMER PRODUCT INCIDENT REPORT

H95B0086A

Narrative Continued
11/8/95 Consumer took oven to dealer, reported incident to dealer's store manager (name unknown), who referred consumer to manufacturer for repair or replacement. 11/95 Consumer plans to report incident to manufacturer and request a refund.
Distributor phone #: unknown
IPSC Source: TV